

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	24	("3997182" "4420166" "4865340" "5207439" "5393081" "5577568" "5799959" "6062328" "6302414" "6488304" "6601859").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:08
S2	4604	Chambers.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 14:24
S3	452	S2 and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 14:24
S4	16	S2 and motor same axle	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 14:25
S5	10188	(180/19.1 180/19.3 180/11 180/16 180/209 180/216 180/65.1 180/65.5 180/65.6 180/907 180/908 280/47.27 280/47.131 280/47.34 280/47.35).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:13
S6	2	S5 and (ptfe polytetrafluoroethene)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:15
S7	89	S5 and ((hand near4 (truck doly cart)) same slide)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 17:08
S8	91	S5 and ((hand near4 (truck doly dolly cart)) same slide)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:31

S9	5	S8 and ((nylon plastic resin composite) same slide)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:26
S10	120	S5 and ((hand near4 (vehicle truck doly dolly cart carrier)) same (skid slide))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:31
S11	7	S10 and ((neoprene polys\$5 polyt\$5 nylon plastic resin composite) same (skid slide))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:31
S12	722	S5 and (((vehicle truck doly dolly cart carrier)) same (skid slide))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:31
S13	44	S12 and ((polys\$5 polyt\$5 nylon plastic resin composite) same (skid slide))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 16:32
S14	132	S5 and ((hand near2 (truck dolly cart)) and motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/06 17:09
S15	156	S5 and (((appliance utility hand) near2 (truck dolly cart)) and motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 14:59

S17	114	S16 and motor	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 07:26
S18	89	("1764851" "20030205885" "2154377" "2740484" "2751259" "2844413" "2879858" "2888114" "2992834" "3073614" "3156315" "3167146" "3199621" "3330370" "3356172" "3380546" "3713501" "3731758" "4027889" "4033421" "4215877" "4280578" "4441848" "4697661" "4915185" "5065320" "5311880" "5406674" "5409245" "5531295" "5555949" "5564720" "5685385" "5691584" "5732786" "5746282" "5819863" "6062328" "6123162" "6129166" "6139029" "6260864" "6283496" "6419244" "6533067" "6536709" "6604707" "D424266").PN. OR ("2740484" "2996133" "3362496" "3713501" "3719247" "3876022" "6276471" "6793236").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 07:26
S19	57	S18 and motor	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 09:34

S20	68	(US-20050155799-\$ or US-20030085552-\$ or US-20050023050-\$ or US-20040238241-\$ or US-20030127813-\$ or US-20030094315-\$).did. or (US-6062328-\$ or US-5799959-\$ or US-5577568-\$ or US-5393081-\$ or US-4420166-\$ or US-3997182-\$ or US-3896904-\$ or US-6328319-\$ or US-6220611-\$ or US-6916028-\$ or US-6907949-\$ or US-6732823-\$ or US-6588775-\$ or US-6561745-\$ or US-6536709-\$ or US-6523838-\$ or US-6386560-\$ or US-6343665-\$ or US-6257358-\$ or US-6173799-\$ or US-6123162-\$ or US-6039332-\$ or US-5964313-\$ or US-5820146-\$ or US-5691584-\$ or US-5657828-\$).did. or (US-5584354-\$ or US-5547035-\$ or US-5378004-\$ or US-5261824-\$ or US-5167389-\$ or US-5036929-\$ or US-4960179-\$ or US-4650200-\$ or US-4570732-\$ or US-4570731-\$ or US-4550924-\$ or US-3719247-\$ or US-2740484-\$ or US-6793236-\$ or US-6386552-\$ or US-6276471-\$ or US-6155362-\$ or US-3876022-\$ or US-3713501-\$ or US-4033421-\$).did. or (US-3092200-\$ or US-1488381-\$ or US-3527314-\$ or US-3205963-\$ or US-2906357-\$ or US-2770310-\$ or US-2740484-\$ or US-2674328-\$ or US-2670093-\$ or US-2620041-\$ or US-2571180-\$ or US-2570256-\$ or US-3362496-\$ or US-2996133-\$).did. or (US-6062328-\$ or US-5577568-\$). did.	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/09/07 08:07
S21	59	S20 and motor	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 10:23
S22	9	S20 and (frame same width)	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 09:24
S23	32	S20 and (steer\$4 differential\$4)	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 09:32
S24	32	S20 and (steer\$4 differential\$4 ((left and right) near2 axle))	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 09:33

S25	32	S24 and motor	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 09:53
S26	5	S25 and (frame same (slide slid skid))	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 10:01
S27	7	S21 and (frame same (slide slid skid))	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 10:01
S28	7	S20 and controller	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 10:26
S29	33	S20 and (motor same control\$4)	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 10:32
S30	27	S20 and (((("12" or "24" or twelve twentyfour twenty-four twenty) near4 volt) ("2" two) same batter\$4))	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 10:40
S31	35	S20 and (batteries)	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 15:03
S32	6	S31 and (two near4 batteries)	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 14:49
S33	114	motor same differential same (left and right) near2 axles same wheels	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 14:51
S34	128	motor same differential same (left and right) near2 axles same wheels	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 14:57
S35	0	S34 and handtruck	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 14:57
S36	0	S34 and (hand-truck)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 14:58

S37	0	S34 and (hand near2 truck)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 14:58
S38	2200	(motor\$4 power\$4) same ((appliance utility hand) near2 (truck dolly cart))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 16:36
S39	896	S38 and ((driv\$4 propel\$4) same wheels)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 16:37
S40	209	S39 and ((batter\$4) same motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 16:40
S41	449	S39 and (control\$4 same motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 15:06
S42	14	("3719247" "3952821" "3989116" "4106583").PN. OR ("4570732").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/07 15:14
S43	83283	(motor\$4 power\$4) same ((stroller truck dolly cart))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 16:37
S44	29068	S43 and ((driv\$4 propel\$4) same wheels)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 16:37
S45	3691	S44 and ((batter\$4) same motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 16:40

S46	310	S45 and ((right and left) same axle)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 18:29
S47	5	S46 and drill	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 18:38
S48	0	S34 and drill	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 18:38
S49	5	S40 and drill	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 19:10
S50	2	"6793236"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:21
S51	685	motor same high near2 speed same ((miles adj per adj hour) mph)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:36
S52	405	S51 and (motor same (axle wheels))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:24
S53	301	S52 and (stroller cart truck buggy carrier dolly hand)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:33

S54	386118	truck dolly cart trolley	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:34
S55	105861	S54 and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:34
S56	52057	S55 and wheels	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:35
S57	37190	S56 and (motor same (axle wheel))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:35
S58	27866	S56 and (motor same control\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:36
S59	588	S58 and mph	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:36
S60	259	S58 and (high near2 speed same ((miles adj per adj hour) mph))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/07 22:37